



ANALYTICAL REPORT

International Water Quality Laboratory
 4100-L Delta Drive
 El Paso, TX 79905-4306
 (915) 594-5725

Client: EPCWCID #4
Project: FABENS 011420
Sampling Location: Fabens Distribution System
 215 Oro Place
 Fabens, TX 79838

Requested By: Martin Madrid
 El Paso County WCID #4
 117 E. Main Rd.
 Fabens, TX 79838

mmadrid@epwcid4.com
 Ph: 915-764-2212
 Fax:

Lab ID: 20-01566	Collected: 01/14/2020 08:22	Source: B
Sample ID: 16205 ORO PLACE	Received: 01/14/2020 11:03	County: El Paso
Sampling Source: Sample Station	Reported: 01/24/2020 09:28	PWSID: TX0710018
Sample Type: GRAB	Matrix: Drinking Water	

Parameter	Result	Units	Dil.	RDL	Prepared	By	Analyzed	By	Qual
SM 4500-Cl G DPD Colorimetric									
Chlorine, Free	1.04	mg/L	1	0.10	01/14/2020 12:17	SMP	01/14/2020 12:17	SMP	
SM 9223B Coliforms									
Total Coliform	Absent	P/A	1	1.00	01/14/2020 16:01	GQG	01/14/2020 16:01	GQG	
E. Coli	Absent	P/A	1	1.00	01/14/2020 16:01	GQG	01/14/2020 16:01	GQG	

All results are reported on a wet weight basis unless otherwise stated. The results contained in this report were obtained using IWQL Standard Operating Procedures. These procedures are in substantial compliance with the approved methods referenced and the standard published by The NELAC Institute unless otherwise noted in the Appendix and/or Quality Control sections of this report. This report may not be reproduced, except in full, without written approval from International Water Quality Laboratory.

We value your feedback. Your input and comments help us improve the efficiency of our services. Please send your comments via email to Rawilcox@epwu.org or fax to (915) 594-5430

Richard A. Wilcox
 Laboratory Services Manager



ANALYTICAL REPORT

International Water Quality Laboratory
4100-L Delta Drive
El Paso, TX 79905-4306
(915) 594-5725

Client: EPCWCID #4
Project: FABENS 011420
Sampling Location: Fabens Distribution System
409 LETTUNICH
Fabens, TX 79838

Requested By: Martin Madrid
El Paso County WCID #4
117 E. Main Rd.
Fabens, TX 79838

mmadrid@epwcid4.com
Ph: 915-764-2212
Fax:

Lab ID: 20-01570
Sample ID: 409 LETTUNICH
Sampling Source: Sample Station
Sample Type: GRAB
Collected: 01/14/2020 09:02
Received: 01/14/2020 11:03
Reported: 01/24/2020 09:28
Matrix: Drinking Water
Source: G
County: El Paso
PWSID: 0710018

Table with 10 columns: Parameter, Result, Units, Dil., RDL, Prepared, By, Analyzed, By, Qual. Rows include SM 4500-Cl G DPD Colorimetric (Chlorine, Free) and SM 9223B Coliforms (Total Coliform, E. Coli).

All results are reported on a wet weight basis unless otherwise stated. The results contained in this report were obtained using IWQL Standard Operating Procedures. These procedures are in substantial compliance with the approved methods referenced and the standard published by The NELAC Institute unless otherwise noted in the Appendix and/or Quality Control sections of this report. This report may not be reproduced, except in full, without written approval from International Water Quality Laboratory.

We value your feedback. Your input and comments help us improve the efficiency of our services. Please send your comments via email to Rawilcox@epwu.org or fax to (915) 594-5430

Signature of Richard A. Wilcox
Richard A. Wilcox
Laboratory Services Manager



ANALYTICAL REPORT

International Water Quality Laboratory
4100-L Delta Drive
El Paso, TX 79905-4306
(915) 594-5725

Client: EPCWCID #4
Project: FABENS 011420
Sampling Location: Fabens Distribution System
148 POTASIO
Fabens, TX 79838

Requested By: Martin Madrid
El Paso County WCID #4
117 E. Main Rd.
Fabens, TX 79838

mmadrid@epcwcid4.com
Ph: 915-764-2212
Fax:

Lab ID: 20-01574
Sample ID: 148 POTASIO
Sampling Source: Sample Station
Sample Type: GRAB
Collected: 01/14/2020 08:07
Received: 01/14/2020 11:03
Reported: 01/24/2020 09:29
Matrix: Drinking Water
Source: G
County: El Paso
PWSID: 0710018

Table with 10 columns: Parameter, Result, Units, Dil., RDL, Prepared, By, Analyzed, By, Qual. Rows include SM 4500-Cl G DPD Colorimetric (Chlorine, Free) and SM 9223B Coliforms (Total Coliform, E. Coli).

All results are reported on a wet weight basis unless otherwise stated. The results contained in this report were obtained using IWQL Standard Operating Procedures. These procedures are in substantial compliance with the approved methods referenced and the standard published by The NELAC Institute unless otherwise noted in the Appendix and/or Quality Control sections of this report. This report may not be reproduced, except in full, without written approval from International Water Quality Laboratory.

We value your feedback. Your input and comments help us improve the efficiency of our services. Please send your comments via email to Rawilcox@epwu.org or fax to (915) 594-5430

Richard A. Wilcox
Laboratory Services Manager



ANALYTICAL REPORT

International Water Quality Laboratory
 4100-L Delta Drive
 El Paso, TX 79905-4306
 (915) 594-5725

Client: EPCWCID #4
Project: FABENS 011420
Sampling Location: Martin Madrid
 El Paso County WCID #4
 117 E. Main Rd.
 Construction Sample
 (915) 764-2212

Requested By: Martin Madrid
 El Paso County WCID #4
 117 E. Main Rd.
 Fabens, TX 79838

 mmadrid@epwcid4.com
 Ph: 915-764-2212
 Fax:

Lab ID: 20-01567	Collected: 01/14/2020 08:41	Source: G
Sample ID: 214 SE 7TH ST	Received: 01/14/2020 11:03	County: El Paso
Sampling Source: Sample Station	Reported: 01/24/2020 09:28	PWSID: TX0710018
Sample Type: GRAB	Matrix: Drinking Water	

Parameter	Result	Units	Dil.	RDL	Prepared	By	Analyzed	By	Qual
SM 4500-CI G DPD Colorimetric									
Chlorine, Free	0.88	mg/L	1	0.10	01/14/2020 12:17	SMP	01/14/2020 12:17	SMP	
SM 9223B Coliforms									
Total Coliform	Absent	P/A	1	1.00	01/14/2020 16:01	GQG	01/14/2020 16:01	GQG	
E. Coli	Absent	P/A	1	1.00	01/14/2020 16:01	GQG	01/14/2020 16:01	GQG	

All results are reported on a wet weight basis unless otherwise stated. The results contained in this report were obtained using IWQL Standard Operating Procedures. These procedures are in substantial compliance with the approved methods referenced and the standard published by The NELAC Institute unless otherwise noted in the Appendix and/or Quality Control sections of this report. This report may not be reproduced, except in full, without written approval from International Water Quality Laboratory.

We value your feedback. Your input and comments help us improve the efficiency of our services. Please send your comments via email to Rawilcox@epwu.org or fax to (915) 594-5430

Richard A. Wilcox
 Laboratory Services Manager



ANALYTICAL REPORT

International Water Quality Laboratory
4100-L Delta Drive
El Paso, TX 79905-4306
(915) 594-5725

Client: EPCWCID #4
Project: FABENS 011420
Sampling Location: Fabens Distribution System
801NE 2ND ST
Fabens, TX 79838

Requested By: Martin Madrid
El Paso County WCID #4
117 E. Main Rd.
Fabens, TX 79838

mMadrid@epwcid4.com
Ph: 915-764-2212
Fax:

Lab ID: 20-01571
Sample ID: 801 NE 2ND ST
Sampling Source: Sample Station
Sample Type: GRAB
Collected: 01/14/2020 09:16
Received: 01/14/2020 11:03
Reported: 01/24/2020 09:29
Matrix: Drinking Water
Source: G
County: El Paso
PWSID: 0710018

Table with 10 columns: Parameter, Result, Units, Dil., RDL, Prepared, By, Analyzed, By, Qual. Rows include Chlorine, Free (1.37 mg/L) and Coliforms (Total and E. Coli, all Absent).

All results are reported on a wet weight basis unless otherwise stated. The results contained in this report were obtained using IWQL Standard Operating Procedures. These procedures are in substantial compliance with the approved methods referenced and the standard published by The NELAC Institute unless otherwise noted in the Appendix and/or Quality Control sections of this report. This report may not be reproduced, except in full, without written approval from International Water Quality Laboratory.

We value your feedback. Your input and comments help us improve the efficiency of our services. Please send your comments via email to Rawilcox@epwu.org or fax to (915) 594-5430

Richard A. Wilcox
Laboratory Services Manager



ANALYTICAL REPORT

International Water Quality Laboratory
 4100-L Delta Drive
 El Paso, TX 79905-4306
 (915) 594-5725

Client: EPCWCID #4
Project: FABENS 011520
Sampling Location: Martin Madrid
 El Paso County WCID #4
 117 E. Main Rd.
 Construction Sample
 (915) 764-2212

Requested By: Martin Madrid
 El Paso County WCID #4
 117 E. Main Rd.
 Fabens, TX 79838

mmadrid@epwcid4.com
 Ph: 915-764-2212
 Fax:

Lab ID: 20-01840	Collected: 01/15/2020 08:10	Source: G
Sample ID: 318 AUSTIN	Received: 01/15/2020 09:07	County: El Paso
Sampling Source: Sample Station	Reported: 01/24/2020 09:29	PWSID: TX0710018
Sample Type: GRAB	Matrix: Drinking Water	

Parameter	Result	Units	DIL	RDL	Prepared	By	Analyzed	By	Qual
SM 4500-CI G DPD Colorimetric									
Chlorine, Free	1.07	mg/L	1	0.10	01/15/2020 12:58	SMP	01/15/2020 12:58	SMP	
SM 9223B Coliforms									
Total Coliform	Absent	P/A	1	1.00	01/15/2020 16:01	GQG	01/15/2020 16:01	GQG	
E. Coli	Absent	P/A	1	1.00	01/15/2020 16:01	GQG	01/15/2020 16:01	GQG	

All results are reported on a wet weight basis unless otherwise stated. The results contained in this report were obtained using IWQL Standard Operating Procedures. These procedures are in substantial compliance with the approved methods referenced and the standard published by The NELAC Institute unless otherwise noted in the Appendix and/or Quality Control sections of this report. This report may not be reproduced, except in full, without written approval from International Water Quality Laboratory.

We value your feedback. Your input and comments help us improve the efficiency of our services. Please send your comments via email to Rawilcox@epwu.org or fax to (915) 594-5430

Richard A. Wilcox
 Laboratory Services Manager



ANALYTICAL REPORT

International Water Quality Laboratory
4100-L Delta Drive
El Paso, TX 79905-4306
(915) 594-5725

Client: EPCWCID #4
Project: FABENS 011420
Sampling Location: Fabens Distribution System
1001 Camp St.
Fabens, TX 79838

Requested By: Martin Madrid
El Paso County WCID #4
117 E. Main Rd.
Fabens, TX 79838

mMadrid@epwcid4.com
Ph: 915-764-2212
Fax:

Table with 3 columns: Lab ID, Sample ID, Sampling Source, Sample Type, Collected, Received, Reported, Matrix, Source, County, PWSID.

Main results table with 10 columns: Parameter, Result, Units, Dil., RDL, Prepared, By, Analyzed, By, Qual. Includes rows for Chlorine, Free and Coliforms.

All results are reported on a wet weight basis unless otherwise stated. The results contained in this report were obtained using IWQL Standard Operating Procedures...

We value your feedback. Your input and comments help us improve the efficiency of our services. Please send your comments via email to Rawilcox@epwu.org or fax to (915) 594-5430

Richard A. Wilcox
Laboratory Services Manager



ANALYTICAL REPORT

International Water Quality Laboratory
4100-L Delta Drive
El Paso, TX 79905-4306
(915) 594-5725

Client: EPCWCID #4
Project: FABENS 011420
Sampling Location: Fabens Distribution System
820 NW 5TH ST
Fabens, TX 79838

Requested By: Martin Madrid
El Paso County WCID #4
117 E. Main Rd.
Fabens, TX 79838

mmadrid@epwcid4.com
Ph: 915-764-2212
Fax:

Lab ID: 20-01572
Sample ID: 820 NW 5TH ST
Sampling Source: Sample Station
Sample Type: GRAB
Collected: 01/14/2020 09:30
Received: 01/14/2020 11:03
Reported: 01/24/2020 09:29
Matrix: Drinking Water
Source: G
County: El Paso
PWSID: 0710018

Table with 10 columns: Parameter, Result, Units, Dil., RDL, Prepared, By, Analyzed, By, Qual. Rows include SM 4500-CI G DPD Colorimetric (Chlorine, Free) and SM 9223B Coliforms (Total Coliform, E. Coli).

All results are reported on a wet weight basis unless otherwise stated. The results contained in this report were obtained using IWQL Standard Operating Procedures. These procedures are in substantial compliance with the approved methods referenced and the standard published by The NELAC Institute unless otherwise noted in the Appendix and/or Quality Control sections of this report. This report may not be reproduced, except in full, without written approval from International Water Quality Laboratory.

We value your feedback. Your input and comments help us improve the efficiency of our services. Please send your comments via email to Rawilcox@epwu.org or fax to (915) 594-5430

Richard A. Wilcox
Laboratory Services Manager



ANALYTICAL REPORT

International Water Quality Laboratory
4100-L Delta Drive
El Paso, TX 79905-4306
(915) 594-5725

Client: EPCWCID #4
Project: FABENS 011420
Sampling Location: Fabens Distribution System
1254 POWELL LN.
Fabens, TX 79838

Requested By: Martin Madrid
El Paso County WCID #4
117 E. Main Rd.
Fabens, TX 79838

mmadrid@epwcid4.com
Ph: 915-764-2212
Fax:

Lab ID: 20-01569
Sample ID: 1254 POWELL LN
Sampling Source: Sample Station
Sample Type: GRAB
Collected: 01/14/2020 08:57
Received: 01/14/2020 11:03
Reported: 01/24/2020 09:28
Matrix: Drinking Water
Source: G
County: El Paso
PWSID: 0710018

Table with 10 columns: Parameter, Result, Units, Dil., RDL, Prepared, By, Analyzed, By, Qual. Rows include Chlorine, Free (1.64 mg/L) and SM 9223B Coliforms (Total Coliform and E. Coli, all absent).

All results are reported on a wet weight basis unless otherwise stated. The results contained in this report were obtained using IWQL Standard Operating Procedures. These procedures are in substantial compliance with the approved methods referenced and the standard published by The NELAC Institute unless otherwise noted in the Appendix and/or Quality Control sections of this report. This report may not be reproduced, except in full, without written approval from International Water Quality Laboratory.

We value your feedback. Your input and comments help us improve the efficiency of our services. Please send your comments via email to Rawilcox@epwu.org or fax to (915) 594-5430

Richard A. Wilcox
Laboratory Services Manager



ANALYTICAL REPORT

International Water Quality Laboratory
4100-L Delta Drive
El Paso, TX 79905-4306
(915) 594-5725

Client: EPCWCID #4
Project: FABENS 011420
Sampling Location: Fabens Distribution System
401 1ST ST SW
Fabens, TX 79838

Requested By: Martin Madrid
El Paso County WCID #4
117 E. Main Rd.
Fabens, TX 79838

mmadrid@epcwcid4.com
Ph: 915-764-2212
Fax:

Lab ID: 20-01573
Sample ID: 401 SW 1ST ST
Sampling Source: Sample Station
Sample Type: GRAB
Collected: 01/14/2020 08:31
Received: 01/14/2020 11:03
Reported: 01/24/2020 09:29
Matrix: Drinking Water
Source: G
County: El Paso
PWSID: 0710018

Table with 10 columns: Parameter, Result, Units, Dil., RDL, Prepared, By, Analyzed, By, Qual. Rows include SM 4500-CI G DPD Colorimetric (Chlorine, Free) and SM 9223B Coliforms (Total Coliform, E. Coli).

All results are reported on a wet weight basis unless otherwise stated. The results contained in this report were obtained using IWQL Standard Operating Procedures. These procedures are in substantial compliance with the approved methods referenced and the standard published by The NELAC Institute unless otherwise noted in the Appendix and/or Quality Control sections of this report. This report may not be reproduced, except in full, without written approval from International Water Quality Laboratory.

We value your feedback. Your input and comments help us improve the efficiency of our services. Please send your comments via email to Rawilcox@epwu.org or fax to (915) 594-5430

Richard A. Wilcox
Laboratory Services Manager